

# **SuperKEKB Status**

Hitoshi Sugimura  
on behalf of SuperKEKB Commissioning Group

# Outline

**Highlights of 2025c operation**

**Work during winter shutdown**

**2026ab operation schedule**


# Overview of 2025c operation

## Luminosity

- Peak Luminosity :  $3.4 \times 10^{34} \text{cm}^{-2}\text{s}^{-1}$ 
  - $\Rightarrow \sim 67\%$  of the 2024c record ( $5.1 \times 10^{34} \text{cm}^{-2}\text{s}^{-1}$ )
- Integrated Luminosity / day
  - $2.49 \text{ fb}^{-1}$  (delivered),  $2.19 \text{ fb}^{-1}$  (recorded)
- Integrated Luminosity / 2025c
  - $28.7 \text{ fb}^{-1}$  (delivered),  **$24.0 \text{ fb}^{-1}$  (recorded)**
  - $\Rightarrow \sim 50\%$  of the original plan
- Integrated Luminosity from 2019
  - **$599 \text{ fb}^{-1}$  (recorded)**

## Beam Current

- LER :  $1.49 \text{ A}$  / HER :  $1.10 \text{ A}$ 
  - $88\%$  /  $81\%$  of the 2024c operation, respectively




# Operation in 2025c

## Synchrotron Injection

- Conducted in HER from Nov. 6 to Nov. 20.
- It was found that some difficulties
  - Abort orbit tuning
  - Charge leakage into adjacent RF buckets
  - Low injection efficiency
- The injection method was switched to betatron injection

## A total of four QCS quench was occurred


- weak-bend abort (Nov. 25),
- SBL (Dec. 9, 21),
- LER Kicker Misfire (Dec. 18)



# Operation in 2025c

## Sudden Beam Loss

- Compared to the 2024c run, the number of SBL events was significantly reduced.
  - Effect of VACSEAL removal
- Still occurred at LER wiggler sections(D11, D04)




# Major Troubles in 2025c

## Malfunction of Kicker Power Supply (Nov. 25)

- Beam abort due to the weak-bend was occurred
- Large radiation dose to Belle II, QCS quench, and damaged to the D01V1 collimator

## Decrease in the QCS-L liquid helium level

- After the weak-bend abort, the helium supply could not keep up.
- Level recovery work was conducted with QCS-L OFF.
- Helium gas flow of current leads was reduced for lower heat load on Dec. 16. Since then, the level has been kept.



# Countermeasures for Issues and Work During Winter Shutdown


## For HER Abort Kicker PS Malfunction Issue

- Short term countermeasure
  - Keep beam current as long as possible and Belle II detector HV off.
  - Try PS reset.
- Long term countermeasure ⇒ Under consideration

## For QCS-L Liquid He Level adjustment Issue

- We were concerned that the beam might have damaged O-rings at the tip of the cryostat, causing air leak into the vacuum vessel
- Vacuum leak check was tested by warm up vacuum vessel
  - If leak is occurred, the pressure will rapidly increase
  - The result showed the pressure characteristic was same as obtained in 2024
  - ⇒ No Vacuum Leak
- The cause of the origin is unclear, but several other valves were opened and closed at the quench, so these may cause that.

Measured just after 2025c



No difference was observed between the measured results in 2025 and the reference data from 2024. Thus, no increase in matter captured by cryo-pump effect was detected.

# Countermeasures for Issues and Work During Winter Shutdown

## For SBL Issue


- Replaced Bellows Chamber at D04, D11 where vacuum spike was observed.

## For Kicker Misfire Issue

- Optimization of parameters of thyatron

## The other works

- Replace HER D01V1 Collimator jaw
- Replace gasket at LER D10 wiggler section



# 2026ab Operation Schedule

1/26 ~ 6/30

- Operation in June will be decided based on the conditions in May
  - To achieve an integrated luminosity of  $1 \text{ ab}^{-1}$ , we plan to operate as much as possible.

2026a

January 6 days							February 28 days							March 31 days						
Sun	Mon	Tue	Wed	Thu	Fri	Sat	Sun	Mon	Tue	Wed	Thu	Fri	Sat	Sun	Mon	Tue	Wed	Thu	Fri	Sat
27	28	29	30	1	2	3	1	2	3	4	5	6	7	1	2	3	4	5	6	7
4	5	6	7	8	9	10	8	9	10	11	12	13	14	8	9	10	11	12	13	14
11	12	13	14	15	16	17	15	16	17	18	19	20	21	15	16	17	18	19	20	21
18	19	20	21	22	23	24	22	23	24	25	26	27	28	22	23	24	25	26	27	28
25	26	27	28	29	30	31								29	30	31	1	2	3	4

Maintenance day : 2/18

Maintenance day : 3/18

2026b

April 30 days							May 31 days							June 14 days ?, 30 days ?						
Sun	Mon	Tue	Wed	Thu	Fri	Sat	Sun	Mon	Tue	Wed	Thu	Fri	Sat	Sun	Mon	Tue	Wed	Thu	Fri	Sat
28	29	30	1	2	3	4	26	27	28	29	30	1	2	31	1	2	3	4	5	6
5	6	7	8	9	10	11	3	4	5	6	7	8	9	7	8	9	10	11	12	13
12	13	14	15	16	17	18	10	11	12	13	14	15	16	14	15	16	17	18	19	20
19	20	21	22	23	24	25	17	18	19	20	21	22	23	21	22	23	24	25	26	27
26	27	28	29	30	1	2	24	25	26	27	28	29	30	28	29	30	1	2	3	4
							31	1	2	3	4	5	6							

Maintenance day : 4/15 (tentative)

Maintenance day : To be determined

# Operation Plan Based on SKB/B2 Joint Review

1. Establish a stable operation at  $5 \times 10^{34} \text{ cm}^{-2}\text{s}^{-1}$
2. Increase the beam current to reach  $6 \times 10^{34} \text{ cm}^{-2}\text{s}^{-1}$
3. Target an integrated luminosity of  $>400\text{fb}^{-1}$  in 2026ab
4. If achieving  $400 \text{ fb}^{-1}$  appears feasible, reduce  $\beta_y^*$  to target  $10^{35} \text{ cm}^{-2}\text{s}^{-1}$

# Target for Operation in 2026ab

## Maximum Current

- **2.0 A (LER), 1.6 A (HER)**

## Luminosity

- **$6.6 \times 10^{34} \text{ cm}^{-2}\text{s}^{-1}$**


## Ratio of Physics run

- 70%

## Accelerator Efficiency in Physics Run


- 80%
- $\epsilon_{\text{acc}} = \text{Integrated luminosity} / \int L_{\text{peak}} dt$

**If all of the above conditions are satisfied,  
an integrated luminosity of 428 fb-1 can be achieved**



# 2026a run

## Physics Run Started from Jan.30



# Summary

## Highlights of 2025c operation

- Due to various issues, including the weak-bend problem and QCS quenches, the accumulated integrated luminosity reached only about 50% of the originally planned value.

## Work during winter shutdown

- Bellows were replaced as a countermeasure against SBL
- In addition, leak checks of the QCS-L were performed, and no issues were found.


## 2026ab operation schedule

- For the current run period, we have established an operation plan to accumulate more than  $400 \text{ fb}^{-1}$  of integrated luminosity, aiming to ultimately achieve  $1 \text{ ab}^{-1}$ .

# backups

## Cause of problem and accelerator operation in 2026

- The cause of the imbalance between the liquefaction capacity and the heat load after Nov. 25th could not be identified, but any valve leaks may be suspected. There was no change in the recovery **tank** pressure cycle just before and after Nov. 25th, making a sheet leak in this system improbable. However, several other valves were opened and closed at the quench, so these may cause the additional heat load.
- Although the cause remains unclear, **stable operation has been successfully maintained** since Dec. 16th, because the gas flow for current lead was reduced to lower heat load.



One of the vapor cooled current lead



Room temp.

4.5 K